



CASE STUDY : PHOSCRETE F1-VO

Bridge Beam Repair



Location: [CA-70 Bridge, Oroville, CA](#)

Ambient Temperature: [65°F, Sunny](#)

Agency: Sacramento County Department of Transportation

Contact: Craig Bollig, Highway Maintenance Supervisor, Bollig@saccounty.net

Installation Date: 03 November 2016

[Link to Google Photos Album](#)

Installation Notes: Bridge beam was damaged by a vehicle. Site was prepared and cleaned. Phoscrete was installed first with a scrub coat, then in lifts. Using standard tools and water as a bond breaker, the repair was quickly smoothed and finished.