



## CASE STUDY : PHOSCRETE F1-VO

### Precast Panel Repairs - Tunnel



**Location:** [Watson Island, Miami, FL](#)

**Ambient Temperature:** [91°F, Sunny](#)

**Agency:** Bouygues Civil Works Florida

**Contact:**

Wilfredo Espinosa, Precast QA/QC Manager, [wilfredo.espinoza@nicholsonconstruction.com](mailto:wilfredo.espinoza@nicholsonconstruction.com)

**Installation Date:** 27 July 2012

[Link to Google Photos Album](#)

**Installation Notes:** Damaged panels were repaired using Phoscrete F1-VO. Material was hand-packed and trowel-finished, and ground to specifications. Panels were then installed in the Miami Tunnel. Precast manager worked again with Phoscrete on a subsequent project with Nicholson Construction.