



## CASE STUDY : PHOSCRETE F1-VO

### Multiple Vertical Patches



**Location:** [Folsom Dam, Folsom CA](#)

**Ambient Temperature:** [60°F, Sunny](#)

**Agency:** US Bureau of Reclamation

**Contact:** Bill Snider, Engineer Technician, [wsnider@usbr.gov](mailto:wsnider@usbr.gov)

**Installation Date:** 20 October 2015

[Link to Google Photos Album](#)

**Installation Notes:** Multiple instances of spalled concrete on site, many caused by corrosion of reinforcing steel. Damaged and weak concrete was removed using a circular saw and a pick axe. Phoscrete F1-VO was hand packed and trowel finished onto the repairs.