



CASE STUDY : PHOSCRETE VO

Precast Panel Repairs - Tunnel



Location: [Watson Island, Miami, FL](#)

Ambient Temperature: [91°F, Sunny](#)

Agency: Bouygues Civil Works Florida

Contact:

Wilfredo Espinosa, Precast QA/QC Manager, wilfredo.espinosa@nicholsonconstruction.com

Installation Date: 27 July 2012

[Link to Google Photos Album](#)

Installation Notes: Damaged panels were repaired using Phoscrete VO. Material was hand-packed and trowel-finished, and ground to specifications. Panels were then installed in the Miami Tunnel. Precast manager worked again with Phoscrete on a subsequent project with Nicholson Construction.