



CASE STUDY : PHOSCRETE VO

Multiple Vertical Patches



Location: [Folsom Dam, Folsom CA](#)

Ambient Temperature: [60°F, Sunny](#)

Agency: US Bureau of Reclamation

Contact: Bill Snider, Engineer Technician, wsnider@usbr.gov

Installation Date: 20 October 2015

[Link to Google Photos Album](#)

Installation Notes: Multiple instances of spalled concrete on site, many caused by corrosion of reinforcing steel. Damaged and weak concrete was removed using a circular saw and a pick axe. Phoscrete VO was hand packed and trowel finished onto the repairs.